Sample Test Name: Precision Machining




(These items were developed by teachers for the Technical Skills Assessment. Below is a sample item for each program standard.)

Question 1 of 13			
What manufacturing process produces the smallest amount of waste material?			
OA) Collaborative			
OB) Additive			
C) Divisive			
OD) Subtractive			
Question 2 of 13			
What are two ESSENTIAL characteristics of a workstation?			
○ A) Safety, green technology			
○ B) Functionality, design			
C) Cleanliness, access			
OD) Cleanliness, safety			
Question 3 of 13			
What fit tolerance may require the use of a press?			
A) LC - locational clearance fit			
OB) LN - locational interference fit			
C) RF - running fit			
OD) FN - force or shrink fit			

## Question 4 of 13

What is the CORRECT reading of the metric micrometer shown?



- **A)** 6.92 mm
- **B)** 5.42 mm
- **C)** 6.40 mm
- **D)** 5.92 mm

## Question 5 of 13

How does tempering change the properties of a hardened piece of tool steel?

- A) Increases toughness
- B) Increases brittleness
- OC) Hardens
- O) Anneals

## Question 6 of 13

What is the MOST LIKELY problem while drilling a hole with a new bit on the drill press, it makes a squealing sound?

- A) Drill feed is too fast.
- OB) Drill RPM is too fast.
- OC) Drill chuck wobbles.
- O) Drill is dull.

Question 7 of 13		
At whi	ch angle is the compound rest set to cut a 60-degree standard thread?	
() A)	29.5 degrees	
( B)	35 degrees	
( C)	50 degrees	
( D)	89.5 degrees	
Ques	tion 8 of 13	
What i	s the PURPOSE of inspecting the condition of cutting tools?	
() A)	To define cut	
○B)	To determine wear	
( C)	To measure surfaces	
( D)	To prepare parameters	
Ques	tion 9 of 13	
What i	s the step AFTER installing a wheel on the surface grinder?	
( A)	Check the RPM rating of the wheel.	
○ B)	Ring test the wheel.	
() C)	Dress the wheel.	
( D)	Visually inspect the wheel.	
Ques	tion 10 of 13	
What 1	function MUST be activated for a CNC machine to read M01 command?	
( A)	Optional stop	
( B)	Vice stop	
( C)	Emergency stop	
() D)	Block delete	

Question 11 of 13
Which part of the CNC lathe holds all the tools?
A) Tool post
B) Chuck
C) Spindle
OD) Turrets
Question 12 of 13
What is the PURPOSE of the manual jog wheel?
A) To change tools
○ B) To move coolant
C) To move the axis
OD) To run the spindle
Question 13 of 13
Which step is part of the CAD process?
A) Dry running a program
OB) Post-processing
OC) Tool path creation
D) Solid modeling

## Precision Machining Sample Test Answer Key

Question	Answer			
1.	В			
1. 2. 3. 4. 5. 6. 7.	D			
3.	D			
4.	D			
5.	Α			
6.	В			
7.	Α			
8.	В			
9.	С			
10.	Α			
11.	D			
12.	С			
13.	D			